


FIG.1



\* SEND R99 PACKET MEASUREMENT REPORT MESSAGE

\*\* SEND R97 PACKET MEASUREMENT REPORT MESSAGE

\*\*\* SEND R99 PACKET MEASUREMENT REPORT MESSAGE WITH NEW FIELD

'NC MEAS LIST TYPE'

FIG.2